

Message Text

CONFIDENTIAL

PAGE 01 BAMA KO 02745 131038Z

ACTION OC-06

INFO OCT-01 AF-10 ISO-00 CCO-00 FBOE-00 SY-05 A-01

OCL-00 /023 W

-----039416 131145Z /43

R 130905Z JUN 78

FM AMEMBASSY BAMA KO

TO SECSTATE WASHDC 9711

INFO AMEMBASSY ABIDJAN

AMEMBASSY ACCRA

AMEMBASSY MONROVIA

C O N F I D E N T I A L BAMA KO 2745

STATE FOR A/OC, A/FBO, A/SY/FO

ABIDJAN FOR RSO

ACCRA FOR RCO

MONROVIA FOR ATO

E.O. 11652: GDS

TAGS: AFAC, ASEC, ABLD

SUBJ: ROOF RESURFACING AND REMODELING

REF: (A) BAMA KO 1079, (B) OC/PE MEMO DATED FEB 15, 1978

1. PER REFTTEL A, ITEMS 1 A THRU C COMPLETED. ALSO ITEM E, CONSTRUCTION OF PARAPET WALL, IN FINAL STAGES OF COMPLETION. ITEM G, RE-ROOFING OF CHANCERY HAS BEEN STARTED, DESPITE ONSET OF RAINY SEASON WHICH WILL DELAY COMPLETION.

2. ITEM 1 D, INSTALLATION OF NEW AIR CONDITIONING SYSTEM NOT POSSIBLE, AS NEW UNIT HAS ARRIVED IN DAMAGED CONDITION WHICH WILL MOST PROBABLY PRECLUDE INSTALLATION UNTIL REPLACEMENT PARTS ARRIVE. PLEASE REFER TO DRAWINGS OF TWIN CCJYEA CHILLERZN NO. ESP-CONFIDENTIAL

CONFIDENTIAL

PAGE 02 BAMA KO 02745 131038Z

525 PREPARED BY EDWARDS ENGINEERING CORP., AND SUBMITTED WITH REF B. ITEMS LABELED "B", INGERSOLL RAND 1 1/4 X 5HK - 1-4-1 PUMP, CONTAIN SERIOUSLY CRACKED PUMPHEADS AND APPEAR TO HAVE LEAKED RUSTY WATER.

3. DRAWINGS SUBMITTED REF B DO NOT INDICATE THE SIZE AND LOCATION OF ELECTRICAL AND WATER SERVICE LINES NEEDED FOR NEW

AIR CONDITIONING UNIT. AS RE-ROOFING PROJECT NOW IN PROGRSS,
POST WOULD LIKE TO MAKE NECESSARY ROOF PENETRATIONS NOW AND
HAVE ROOFERS RESURFACE AROUND SAME. IF IT IS POSSIBLE TO
USE OR MODIFY EXISTING SERVICE LINES, PLEASE ADVISE HOW THIS
COULD BEST BE DONE.

4. POST, HOWEVER, SUGGESTS SENDING AN EXPERT TO ASSESS DAMAGE
TO NEW UNIT AND TO ADVISE AS TO MOST FAVORABLE LOCATION AND
SIZE OF NECESSARY ROOF PENETRATIONS.
BYRNE

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 13 jun 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978BAMAKO02745
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: GS
Errors: N/A
Expiration:
Film Number: D780246-0790
Format: TEL
From: BAMAKO
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780667/aaaacfsp.tel
Line Count: 72
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: de33d18a-c288-dd11-92da-001cc4696bcc
Office: ACTION OC
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: 78 BAMAKO 1079
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 27 apr 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 2381604
Secure: OPEN
Status: NATIVE
Subject: ROOF RESURFACING AND REMODELING
TAGS: AFAC, ASEC, ABLD
To: STATE
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/de33d18a-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014